IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U. S. Patent: 7,205,953

Examiner:

Trinh Vo Dinh

Issued:

April 17, 2007

Group:

2821

Inventor(s):

Knadle, Jr., et al.

Docket No.

022.0008(1630)

For: DIRECTIONAL ANTENNA ARRAY

CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Attn: Certificate of Corrections Branch

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

Please correct the above-identified patent by issuing a Certificate of Correction for Patent Office mistakes under Rule 1.322 as follows:

Column 7, line 53, "clement" should be changed to --element--;

Column 7, line 65, "ray" should be changed to --array--;

Column 8, line 42, "army" should be changed to --array--;

Column 8, line 58, "element said" should be changed to -- element, said--;

Column 8, line 59, "balum" should be changed to --balun--;

Column 10, line 32, "fixst" should be changed to --first--.

These errors occurred through the fault of the Patent Office and no fee is involved. The issuance of a Certificate of Correction under Rule 1.322 is therefore considered proper.

Respectfully submitted,

Date: May 15, 2007

Ingrassia Fisher & Lorenz, P.C.

<u>/DANIEL R. POTE, REG. # 43011/</u>

By: Daniel R. Pote Attorney for Applicant(s) Tel. (480) 385-5060